
README.TXT

Adaptec ASC-1405/1045 SAS/SATA Controller

as of January 08, 2010

Please review this file for important information about issues and errata's that were discovered after completion of the standard product documentation. In case of conflict between various parts of the documentation set, this readme file contains the most current information.

NOTE: The latest BIOS, driver and documentation can be downloaded from www.adaptec.com when they become available.

The following information is available in this file:

1. Software and Documentation
 - 1.1 Controller & Utility Software
 - 1.2 Operating System Support
2. Installation Instructions
 - 2.1 Software
 - 2.2 Hardware
3. Known Limitations

1. Software and Documentation

1.1. Controller & Utility Software

Note: The latest versions of BIOS and driver software can be downloaded from www.adaptec.com when they become available.

- BIOS
- Operating System Drivers

1.2 Operating System Support

Windows:

- 32-BIT WINDOWS OPERATING SYSTEMS SUPPORT
 - Microsoft Windows Server 2003 (Standard, Enterprise,& Web Editions) Service Pack 2
 - Microsoft Windows XP Professional Service Pack 3
 - Microsoft Windows Vista Service Pack 2
 - Microsoft Windows Server 2008 Service Pack 2
 - Microsoft Windows 7, All versions
 - Microsoft Windows Server 2008R2, Enterprise, Standard, Datacenter
- 64-BIT WINDOWS OPERATING SYSTEMS SUPPORT
 - Microsoft Windows Server 2003 (Standard, Enterprise Editions) Service Pack 2
 - Microsoft Windows XP Professional Service Pack 2
 - Microsoft Windows Vista Service Pack 2
 - Microsoft Windows Server 2008 Service Pack 2
 - Microsoft Windows 7, All versions
 - Microsoft Windows Server 2008R2, Enterprise, Standard, Datacenter

Linux:

- 32-BIT LINUX OPERATING SYSTEMS SUPPORT
 - Red Hat Enterprise Linux 4.0
 - Red Hat Enterprise Linux 4.0 QU6
 - Red Hat Enterprise Linux 5.0

README.TXT

- Red Hat Enterprise Linux 5.0 QU2
- Red Hat Enterprise Linux 5.0 QU3
- SuSE Linux Enterprise Server 9
- SuSE Linux Enterprise Server 9 SP4
- SuSE Linux Enterprise Server 10
- SuSE Linux Enterprise Server 10 SP2

- 64-BIT LINUX OPERATING SYSTEMS SUPPORT

- Red Hat Enterprise Linux 4.0
- Red Hat Enterprise Linux 4.0 QU6
- Red Hat Enterprise Linux 5.0
- Red Hat Enterprise Linux 5.0 QU2
- Red Hat Enterprise Linux 5.0 QU3
- SuSE Linux Enterprise Server 9
- SuSE Linux Enterprise Server 9 SP4
- SuSE Linux Enterprise Server 10
- SuSE Linux Enterprise Server 10 SP2

2. Installation Instructions

2.1 Software

- For installation instructions, refer to the SAS/SATA Adaptec Controller Installation and User's Guide.

2.2 Hardware

- Hardware installation instructions are also detailed in the product documentation.

3. Known Limitations

- 3.1 BIOS supports maximum up to 128 devices, which includes all types i.e. SES, SAS/SATA drives, Tapes and CD/DVD Roms.
- 3.2 The BIOS does not remap/rebuild the failed sectors during verification.
- 3.3 BIOS does not support SMART 6 implementation.
- 3.4 The failed drives that are still detected, BIOS displays "disk error" during POST and "0 MB" in CTRL + A utility.
- 3.5 BIOS is unable to detect the removable media devices of ATA8 implementation.
- 3.6 Driver does not support IT Nexus time-out. For example, when any device is unplugged during system operation, it removes the device entry.
- 3.7 Adding more Adaptec S50 Enclosure drives drastically slows down the booting time in Windows 2003. For example, when there are 4 Adaptec S50 Enclosure (SAS/SATA drives) attached to the system, booting the splash screen to the logon prompt takes approximately 4 minutes. Similarly, when there are 9 Adaptec S50 Enclosure attached to the system, the login prompt appears after 15 mins. Hence, according to the number of Adaptec S50 Enclosure attached to the system, the booting of the OS drastically slows down to load the login prompt.
- 3.8 % symbol for formatting operation is not displayed for SATA drives. SATA drives do not support background formatting, and it is a busy-wait process. Once you quit the process, the formatting stops, hence % display is not applicable for SATA drives.
- 3.9 BIOS user interface does not confirm any of the user changes.
- 3.10 The product is shipped with the RPM for out-of-the-box kernel and upgraded kernel. For instance, SLES 9 RPM's are shipped for SLES 9 OOB and SLES 9 SP4. If the user is currently using SLES9 and has plans to upgrade to the latest kernel, then it is recommended to upgrade the kernel first and use the RPM for the upgrade kernel.
- 3.11 BIOS and Driver does not support SC933EL2 Enclosures, when connected with SATA drives.
- 3.12 A delay of two minutes is introduced in BIOS to discover slower devices such as Seagate Hard Disk, Hitachi Hard Disk, Tape Drives etc.
- 3.13 The following are the combination of SAS and/or SATA drives with maximum and minimum drive support for I/O performance.
 - 24 SATA drives through two enclosures - 26 devices
 - 60 SAS drives through five enclosures - 65 devices

README.TXT

- 16 SATA drives and 48 SAS drives through six enclosures - 70 devices
 - 12 SATA drives and 60 SAS drives through six enclosures - 78 devices
- 3.14 The user is recommended to add only single enclosure in the SAS/SATA ecosystem.
- 3.15 The 64 Bit Driver will support maximum up to 16 GB System memory under 64 bit Operating Systems.
- 3.16 BIOS Format, Verify and Blink-LED operation from Ctrl-A utility may not work with target devices which support Multi-LUN (ex. RBOD devices).
- 3.17 Installation on 128th LUN will fail as driver supports only 127 LUNS.
- 3.18 Linux OS installation will not work on LUNS greater than 8 due to OS limitation.
- 3.19 If there is no LUN 0 in Multi LUN device(RBOD), windows XP 32 bit OS will not detect other LUNS created in the device
- 3.20 On windows operating systems, the format operation on a LUN could fail on the the InfoTrend RBOD, after the LUN is re-created after deletion. The workaround for this issue is to reboot the operating system, after which this issue will disappear.
- 3.21 On windows operating systems, the format operation on a LUN could fail on the the InfoTrend RBOD, after the LUN is re-enabled after disable operation. The workaround for this issue is to reboot the operating system, after which this issue will disappear.
- 3.22 When the Quick Boot option is enabled in the CTRL-A BIOS, the default discovery time per device is 4 seconds (configurable), any devices not discovered in that time will not be displayed on the console. A message will be displayed during the POST that this option is enabled.

(c) 2009 Adaptec, Inc. All Rights Reserved.

This software contains the valuable trade secrets of Adaptec or its licensors. The software is protected under international copyright laws and treaties. This software may only be used in accordance with the terms of its accompanying license agreement.

No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without prior written consent of Adaptec, Inc., 691 South Milpitas Blvd., Milpitas, CA 95035.